



DEPARTMENT OF THE NAVY

COMMANDER
TRAINING AIR WING FIVE
7480 USS ENTERPRISE STREET SUITE 205
MILTON, FLORIDA 32570-6017

IN REPLY REFER TO
COMTRAWINGFIVENOTE 3710
N71
22 Oct 15

COMTRAWING FIVE NOTICE 3710

Subj: RESCINDED READ AND INITIAL (T-6B)


Encl: (1) Previously Rescinded Read and Initials (T-6B)

1. The following Training Air Wing FIVE Read and Initial has been rescinded and is no longer required to be maintained by subordinate commands. Enclosure (1) is a list of previously rescinded Read and Initials for T-6B Advisories.

T-6B PCL Finger Lift Guard. 09OCT13

Reason for rescinding: Information has been incorporated into the T-6B NATOPS Flight Manual Change 4.

2. Cancellation Contingency. All previous editions of this notice are hereby cancelled.



G. A. KLING

Distribution:

VT-2, 3, 6, 10, 27, 28, FITU, USNTPS, VX-20

T-6A NATOPS Program Manager

T-6B NATOPS Program Manager

Previously Rescinded Read and Initials (T-6B)

1. Rescind Date: 05Oct15 and 31AUG15. T-6 Fuel Nozzle Malfunction. 31OCT14

Reason for rescinding: This Read and Initial was temporarily issued to cover aircraft affected by faulty fuel nozzles. The CNATRA Class Desk reports that all affected T-6 fuel nozzles have been subsequently identified, removed, and replaced.