



**DEPARTMENT OF THE NAVY**

COMMANDER  
TRAINING AIR WING FIVE  
7480 USS ENTERPRISE STREET SUITE 205  
MILTON, FLORIDA 32570-6017

IN REPLY REFER TO:  
COMTRAWINGFIVENOTE 3710  
N7  
7 Dec 15

COMTRAWING FIVE NOTICE 3710

Subj: RESCINDED READ AND INITIAL LIST (TW-5 VT/FITU)

Encl: (1) TW-5/T-6B Active Read and Initial List

1. The following Training Air Wing FIVE Read and Initial has been rescinded and is no longer required to be maintained by subordinate commands.

2. Reason for rescinding: T-6Bs will no longer be actively parked along rows I and J. Refer to COMTRAWINGFIVEINST 3710.2W (FWOP) for KNSE taxi procedures to the alternate run-up.

- KNSE TAXI PROCEDURES FOR ROWS I AND J 19FEB15

  
G. A. KLING

Distribution:  
COMTRAWINGFIVEINST 5216.1U  
Lists II (a-c, e-f, i, k, q-t), List III (h)  
TW-5 T-6B Standardization Officer

TW-5/T-6B  
ACTIVE READ AND INITIAL LIST

| <u>Title</u>   | <u>Serial</u> | <u>Date</u> |
|--|---------------|-------------|
| 1. 15-007: EJECTION SEAT SEQUENCING                          | N7/663        | 26JUN15     |
| 2. FAULTY ENGINE DATA MANAGER (EDM)                          | N7/1119       | 03NOV14     |
| 3. PHANTOM MASTER WARNING AND CAUTIONS                       | N7/1092       | 23OCT14     |
| 4. POTENTIAL FOR DELAYED INFLATION OF LPU-23<br>WAIST LOBES  | N3/666        | 08JUL14     |
| 5. RUDDER BINDING/JAMMING                                    | N7/561        | 11JUN14     |
| 6. UPGRADED OBOGS CONCENTRATOR FLEET<br>ASSESSMENT           | N7/443        | 08MAY14     |
| 7. SEA WATER ACTIVATED RELEASE SYSTEM<br>(SEAWARS) DAMAGE    | N8/211        | 06MAR14     |
| 8. ADVANCE OUT-OF-CONTROL FLIGHT (OCF) FLIGHT<br>RESTRICTION | N3/1063       | 03OCT13     |
| 9. V-BRACE ATTACHMENT BOLT                                   | N3/622        | 31MAY13     |
| 10. RADALT ALT FAIL MODE                                     | N3/720        | 24JUL12     |