



DEPARTMENT OF THE NAVY

COMMANDER TRAINING AIR WING SIX
390 SAN CARLOS ROAD SUITE C
PENSACOLA, FLORIDA 32508-5509

Canc frp: Sep 17

COMTRAWINGSIXNOTE 3750
OOS
23 Sep 16

COMTRAWINGSIX NOTICE 3750

From: Commander, Training Air Wing SIX

Subj: COMPOSITION OF MISHAP BOARDS

Ref: (a) OPNAVINST 3750.6S
(b) CNATRAININST 3750.26H
(c) COMTRAWINGSIXINST 3750.6B

1. Purpose. Designate Primary and Alternate mishap board members.
2. Action. Per reference (a), the following personnel are designated Mishap Board members and will familiarize themselves with the contents of references (b) and (c).
3. The Mishap Board member assignments are as follows:

a. Primary Mishap Board

Senior Member: CDR E. Turcotte
Aviation Safety Officer: LCDR B. Holbus
Flight Surgeon Member: LT H. Reynolds
Operations Representative: Maj J. Brockmeier
Maintenance Representative: LCDR C. Xander

b. Alternate Mishap Board

Senior Member: TBD BY TRAWING SIX
Aviation Safety Officer: TBD BY TRAWING SIX

COMTRAWINGSIXNOTE 3750
23 Sep 16

Flight Surgeon Member: TBD BY TRAWING SIX

Operations Representative: TBD BY TRAWING SIX

Maintenance Representative: TBD BY TRAWING SIX

4. At the time a board is convened, the Senior Member may request additional members as he deems appropriate per reference (a).
5. In the case of a class "A" flight related mishap, the Senior Member will be an O-5 designated by COMTRAWING SIX. In order to maintain safety privilege, no aircraft mishap board members may be assigned the concurrent JAG Manual investigation.
6. Records Management. Records created as a result of this notice, regardless of media and format, must be managed per Secretary of the Navy Manual 5210.1 of January 2012.



MARK G. STOCKFISH

Releasability and distribution:

This notice is cleared for public release and is available electronically only via TW-6 Website, <https://www.cnatra.navy.mil/tw6/>